



# Strain Gauge Instrumentation Amplifier


When no strain gauges are connected, two 120 Ohm resistors should be placed instead on connector P2








# Hall Sensor Amplifier



# Motor Amplifier



Title		Amplifier for Haptic Paddle	
Size	Number	Revision	B
A4	1/2		
Date:	10/2/2012	Sheet of	
File:	D:\Users\Amplifier.SchDoc	Drawn By:	Leuenberger



Title			
Powersupply for Haptic Paddle			
Size	Number	Revision	
A4	2/2	B	
Date:	10/2/2012	Sheet of	
File:	D:\Users\...\Power Supply.SchDoc	Drawn By:	Leuenberger