After downloading, unblock the 'CFH_SkyPlugin.dll' file:

and copy it into the directory 'Plugins' located in the SkySonde Client installation path, typically 'C:\Program Files (x86)\SkySonde Client'.

SkySonde Client Version 1.1.8.4 or later is required.

During the client startup phase, enable the 'EnSci CFH' plugins on the 'Other' tab: